

INSPECTION REPORT
OF ACQUIRED PROPERTY

Block 10 Parcel No. 7 Area R 50

Street and No. 193 Lyndon Row

Date of Option _____ Date Accepted _____

Date of Inspection 2/25/65 Occupied: Yes yes No _____

If yes by whom: _____

Owner _____ Tenant _____ No. of Rooms: 5

No. of Floors: _____

Living Room 1 Bed Rooms 3 Dining Room 0

Kitchen 1 Other _____

Plumbing: Lavatory ✓ Tub no Shower no

Hot Water Heater no Gas or Electric _____ Condition _____

Make and Model _____

Kitchen Sink yes

Heating: Type Used: Gas

No. Two Space Heaters Condition Good

Refrigerator: yes Range Electric

General Condition of Interior: fair Exterior fair

Remarks: 5-19-65

This property was burned by Fire Dept. in order to speed up progress of putting in sewer line.

Inspected by: H. Simmons